

• Up to 201,600 rpm

• Maximum continuous power 41 watts

Slotless design is cog free, and provides high efficiency and cool operation at high speed. Large bearings for long life. 150°C rated Neo rare earth magnets standard. Available with 120° hall sensors or sensorless. Hall sensors recommended for positioning or where a significant inertial load is attached to the shaft. The V (vacuum compatible option) has all non outgassing materials suitable for vacuum use and ceramic hybrid ball bearings. Special modifications are possible such as custom shaft lengths,




Motor Data

Winding		2575	12600
Nominal supply voltage	volts	24	16
no load speed	rpm ±12%	61,800	201,600
speed/torque slope	rpm/oz-in	11,403	26,650
Stall torque (theoretical)	oz-in	11.8	9.7
Continuous torque case 20°C/no h.s.	oz-in	1.4/7	.5/0
Continuous current case 20°C/no h.s.	amps	4.0/1.4	6.9/.35
Motor constant Km	oz-in/√w	.40	.26
Winding resistance not including leads	ohm±15%	1.00	.13
Peak output	watts	111	356
No load current	amp±50%	.23	.60
Damping factor	oz-in/krpm	.0016	.00026
Static friction	oz-in	.023	.012
Velocity constant	rpm/volt	2,575	12,600
Torque constant Kt	oz-in/amp	.52	.108
Stall current	amps	24.0	113
Maximum efficiency	%	81	86
Winding inductance	mH	.12	.005
Mechanical time constant	ms	10	24
Rotor inertia	10 ⁻⁴ oz-in-sec ²	.111	.111
Thermal res. winding to case	°C/W	5.2	5.2
Thermal case to ambient	°C/W	4.3	4.3
Weight	7 oz		

Maximum winding temperature 125°C

values based on winding and magnet temperature of 20°C. Phase lead are 12" minimum and untrimmed lead resistance is .052Ω. Excess lead length should be trimmed. Phase leads are 24 gauge stranded TFE insulated, and hall leads are 28 gauge, TFE insulated. Axial force on bearing including during installation should not exceed 25 lb.



Leads	
Blue	Phase A
White	Phase B
Brown	Phase C
Red	+5 volts
Black	Ground
Yellow	Sensor A
Orange	Sensor B
Green	Sensor C

Ordering Information: mail@koford.com • phone 330-315-3061 • fax 937-695-0237 • www.koford.com

Example: Part Number 48 H 2575 A / A3

Motor dia. _____ Encoder A5=500lines(2,000 count)

Type S=sensorless H=120°halls _____ Modifications A=none, V=Vacuum compatible

Winding number _____

Unit conversions

$^{\circ}\text{F} - 32 \div 1.8 = ^{\circ}\text{C}$ example: $212^{\circ}\text{F} = 100^{\circ}\text{C}$, $^{\circ}\text{C} \times 1.8 + 32 = ^{\circ}\text{F}$ example: $100^{\circ}\text{C} = 212^{\circ}\text{F}$, $\text{in} \times 25.40 = \text{mm}$,
 $\text{mm} \times 0.03937 = \text{in.}$, $\text{oz} \times 28.3495 = \text{g}$, $\text{oz-in} \times 7.06 = \text{mNm}$, $\text{mNm} \times .142 = \text{oz-in}$, $\text{Nm} \times .142 = \text{oz-in}$,
 $\text{Ncm} \times 1.42 = \text{oz-in}$, $\text{rpm} \times .1047 = \text{rad s}^{-1}$, $\text{V/R/S} \times .1047 = \text{volts/rpm}$, $746 \text{ watts} = 1\text{hp}$, $\text{lb-in}^2 \times$
 $.04144 = \text{oz-in-sec}^2$

Balancing

Components attached to the motor shaft should be dynamically balanced to G6.3 or better and located as close to the motor body as possible. G6.3 is equal to $0.64 \times \text{weight (oz.)}/\text{rpm} = \text{unbalance in milli oz-in}$. If the components have appreciable length they must be balance in 2 planes.

Motor technology

The Koford 48HS brushless series of motors are high speed slotless sintered rare earth permanent magnet motors with unique technology. Compared to other brushless motors they have higher speed capabilities, better efficiency, lighter weight and more durable construction (ML Class 220C wire insulation bonded with solventless Class 205 thermoset resin) compared to the low temp bondable wire used in other slotless motors which will soften and fail under thermal overload.

Operating speed

Motors can be operated at any voltage lower than the specified voltage. Motors must not be operated over the maximum speed listed. To obtain speeds over 100,000 rpm the S18V15A drive must be used. Hall drives are not recommended for speeds over 60,000 rpm.

Motor selection

Hall sensor motor can start large inertial loads. For this reason they are most suitable for applications such as beam choppers providing that a speed above 60,000 rpm is not required. If higher speeds are required then a sensorless motor must be used with the S18V15A drive. This drive requires operation from a variable voltage power supply with a current limit of 15 amps or less. For most applications a 3 to 5 amps supply will be suitable. These power supplies are readily available for electronics distributors.

Speed torque calculations

A motors no load speed is equal to the supply voltage times the velocity constant (rpm/v). Under load the rpm will drop. To determine the approximate speed, use dyno data if listed, or use the speed torque slope from the data sheet. For example if the supply voltage is 28 volts and the rpm/volt is 500 then the no load speed will be 14,000 rpm. If the speed torque slope is 800 rpm/oz-in and a 5 oz-in load is applied to the shaft then the speed will be $14,000 - (5 \times 800) = 10,000$ rpm. If there is extra wiring between the drive and the motor, or the supply and the drive, then the speed will drop at a more rapid rate due to the voltage drop in the wiring. A design margin of at least 15% should be used to allow for motor tolerances, so for example with the above motor the rpm can be expected to be at least 8,695 rpm.

Motor cooling

The continuous output torque which can be achieved from a motor is limited by the allowable maximum temperature. This in turn is determined by the cooling provided by the user, and the ambient temperature. The 20°C continuous torque values listed are based on the motor housing being held to 20°C by such means as a refrigerated cooling jacket clamped to the OD of the motor. If the ambient temperature is above 20°C then the continuous duty torque is reduced.

Vacuum Applications

Standard motors are suitable for low vacuum applications. For high vacuum applications use (option V). Vacuum grade motors are made with low outgassing material and baked before shipping. A vacuum bake by the customer immediately prior to use may be desirable to reduce initial pump down time. An important consideration is that

in a vacuum there is no heat removal by air contacting the motor housing. Therefore the mounting of the motor should be made of highly thermally conductive material, such as copper or aluminum, should be of as heavy a cross section as possible, and should connect to a large surface exposed to the outside air. A liquid cooling jacket with a heat exchanger can also be used for the ultimate performance.

Motor hook up

Koford hall sensor motors typically separate the phase and sensor wires. These wires should be kept apart and away from other wires. The leads should be trimmed as short as possible to reduce EMI and power losses. Where electrical noise is a consideration the phase wires may be twisted or braided with each other or enclosed in a shielded jacket. The same can be done with the hall leads to prevent their picking up EMI from noise sources.

EMI

Koford drives and motors have low levels of emi relative to other motors but in sensitive applications the following steps are suggested. First keep the phase wires as short as physically possible and twist or braid them together and if necessary add a shield jacket terminated at one end. Add a 5,000 μ F cap at the input to the drive along with a common mode inductor. Add small inductors to each of the phase wires. If possible vary the input voltage to the drive rather than using the speed control. Place the drive and motor as close together as possible. Also consider enclosing the drive or motor and drive in a metal enclosure.

PWM basics

Variable speed drives operate using PWM where the voltage to the motor is rapidly turned on and off. This is the same as a switching power supply where the motor is the filter. A PWM drive operates like a transformer, for example if the motor pulls 20 amps at 12 volts and the input to the drive is 36 volts then the input current to the drive will be $12/36 \times 20$ or 6.66 amps (neglecting losses). A drive rated at 20 amps will only pull 20 amps from the power supply or battery if the speed is turned all of the way up (no PWM). The S18V15A drive does not use PWM so this is not applicable. With this drive the motor current will be the same as the power supply current.